

Technical Bulletin: Color Block DB4 Output Flicker

Overview

Although not noticeable live, in certain circumstances a flicker can be perceived on camera when using Color Blocks with High Definition or high-speed cameras. This flicker can normally be resolved satisfactorily by camera adjustment; however, Spectrum Manufacturing have developed a software modification to resolve this issue if camera adjustment is not possible. Only the following serial numbers are affected:

Start	Stop	Start	Stop	Start	Stop
505017249	505017290	505018781	505018801	306022345	306022384
505017334	505017335	505019203		306022388	306022395
505017382	505017555	505019400	505019419	306022400	306022402
505017559	505017608	505019440	505019457	306022431	306022504
505017669	505017748	505019477	505019493	306022571	306022677
505017756	505017805	505019691	505019693	306022797	306022902
505017861	505017879	505019712		306023056	306023163
505017881	505017960	505020119	505020123	306023166	306023185
505017982	505018010	505020699	505020876	306023190	306023191
505018244	505018331	505021124	505021181	306023295	306023394
505018336	505018347	505021211	505021306	306023421	306023529
505018349	505018388	505021501	505021635	306023604	306023613
505018391	505018436	505021693	505021769	306023687	306023721
505018440	505018509	505021850	505021948	306025139	306025141
505018522	505018579	505022077	505022078	306025665	306025670
505018610	505018619	505022085	505022097	306025697	306025704
505018721	505018727	505022294	505022343	306025768	306025769

The modification can be carried out free-of-charge at the A.C. Entertainment Technologies facility in High Wycombe UK or A.C. Lighting Inc facility in Toronto, Canada. All shipping costs are chargeable. Please contact the A.C. Entertainment Technologies technical sales departments for details.

Note: While all due care has been taken in the preparation of this document, Chroma-Q shall not be liable for any inaccuracies or omissions which may occur herein.