

LumiNode / LumiCore

Release notes.

Version 2.6.2

Related products: LumiNode range, LumiCore range



With this release, Luminex introduces bug fixes and WebUI improvements.

Bug Fixes

- Improved timing for DMX/RDM packets to prevent packet drops when LumiNode handles a large number of packets simultaneously. This mainly enhances the performance of the LumiNode12 and LumiNode12RJ45 models.
- Resolved an issue where network configuration could be lost after a device reboot.
- Fixed an issue that prevented selecting sACN as the protocol for contact closure.
- Resolved an LCD issue where the configuration was not displayed correctly when a process engine had multiple DMX output ports.
- Fixed an issue where the web interface displayed an error when changing the process engine mode to one with fewer inputs.
- Added a PoE icon to the Ethernet port in the advanced network page to easily identify which port receives PoE power.

