GigaCore
ETHERNET SWITCHES

Release notes.

Version 3.1.2

Related products: GigaCore 10, 12, 14R, 16Xt, 16RFO, 26i

This release addresses a few issues related to the boundary clock features.

New Features

- No new features are introduced in this release.

Bug Fixes

- Custom boundary clock profile settings were not being stored correctly. This has now been fixed, and the sync interval parameter is now reboot-persistent.

- The units for the sync receipt timeout and announce receipt timeout parameters in custom boundary clock profiles were previously incorrect. This has now been corrected.