GigaCore
ETHERNET SWITCHES

Release notes.

Version 1.3.2

Related products: GigaCore 10i, 16i, 30i, 16t, 18t, 20t

With this release, Luminex brings bug fixes that improve boundary clocking as well as AVB stability.

New Features

■ No new features are introduced in this release.

Bug Fixes

■ An issue was resolved where, in a setup with many talkers of the same manufacturer ID in the network, the MRPDU packet size for AVB could be exceeded. This has been solved, resulting in more stability for the end points.

■ A bug was fixed where Tx timestamps were dropped on tagged traffic, resulting in boundary clocking not functioning satisfactory on ISL and custom trunk connections.

■ An issue was resolved to improve boundary clock interoperability and synchronization with specific PTPv2 devices.